

Nepshaw Lane South, Morley, Leeds, LS27 7JQ Materials Testing Manager: D. J. Brockbank

t: 0113 393 9791

e: dbrockbank@wyjs.org.uk www.wyjs.org.uk/materialstesting



TEST REPORT

Client: Camira Fabrics Ltd

> Meltham Mills Meltham West Yorkshire

HD9 4AY

Entry No: 70209 (amended)

Date received: 15/05/2015

Client's Description: Sample of fabric: Synergy

Test Required: Pilling

Conditioning: In accordance with BS EN ISO 139: 2005 for a minimum of 24 hours at

65+/4%, Relative Humidity, 20+/-2°C

Date Tests Completed: 21/05/2015

Pilling: BS EN ISO 12945-2: 2000 Load 415g

Rating

After 2,000 rubs After 5,000 rubs

This is hereby certified to be a correct return of the tests made of the items referred to herein

Vivienne Brockbank Senior Technician

Date of original 26 May 2015

Date of amendment 05 February 2016

Unless instructed otherwise by the client sample remnants will be disposed of after 28 days.

- Tests marked ^N in this certificate are not included in the UKAS Accreditation Schedule for this Laboratory. Tests marked ^F in this certificate are performed under the Laboratory's Flexible Scope of Accreditation. Tests marked ^S in this certificate have been subcontracted to another ISO17025 Accredited Laboratory.
- Opinions and interpretations expressed herein are outside the scope of UKAS accreditation.
- Uncertainty budgets for test methods contained within this report are available on request. This Certificate relates only to the sample received and, unless that sample has been drawn by the staff of this laboratory, or its agent, and endorsed accordingly, any application of the result to a bulk quantity or other material is entirely the responsibility of the client.



